

# REPORT

# Attachments to the technical description

Maintenance Embassy of Croatia

Client: Embassy of Croatia

Reference:BJ1462-RHD-XX-XX-RP-X-0002Status:Draft/01

30

Date: 30 June 2023



#### HASKONINGDHV

Contactweg 47 1014 AN Amsterdam Netherlands Industry & Buildings

+31 88 348 95 00 T info@rhdhv.com E

royalhaskoningdhv.com W

Document title:	Attachments to the technical description
Reference: Your reference Status: Date: Project name: Project number:	Maintenance Embassy of Croatia BJ1462-RHD-XX-XX-RP-X-0002 Click or tap here to enter text. Draft/01 30 June 2023 Maintenance BJ1462 Fréderique Sonnemans
Drafted by:	Frederique Sonnemans
Checked by:	
Date:	
Approved by:	
Date:	
ification	
dential	

Unless otherwise agreed with the Client, no part of this document may be reproduced or made public or used for any purpose other than that for which the document was produced. HaskoningDHV accepts no responsibility or liability whatsoever for this document other than towards the Client.

Please note: this document contains personal data of employees of HaskoningDHV. Before publication or any other way of disclosing, this report needs to be anonymized, unless anonymisation of this document is prohibited by legislation.

Class Confi



### Introduction

This photo attachment belongs to the technical description BJ1462\_Technical description\_Groot hertoginnelaan 30\_The Hague\_DUTCH\_30230630.

This attachment gives a brief description of each STABU chapter and refers to the relevant restoration category from the restoration ladder in which the component will be restored.

Tabel 1: Hiërarchie van restauratiecategorieën (restaura	tieladder)
--	------------

Restauratiecategorie		Toelichting
1. Conserveren / on	derhoud	
2. Repareren		
3. Vernieuwen	a. Kopiëren	Zelfde vorm, zelfde (gelijksoortig) materiaal, zelfde verbindingstechniek
	b. Imiteren	Zelfde vorm, ander materiaal en/of andere verbindingstechniek
	c. Verbeteren	Verbeteren prestatie; oorspronkelijke of aangepaste vorm, ander materiaal en/of andere verbindingstechniek.

Restoration category Explanation

- 1. Conservation/maintenance
- 2. Repair
- 3. Renew a. Copy Same shape, same (similar)

material, same joining technique

b. Imitate Same shape, different material and/or

other joining technique

c. Improve Improve performance; original

or adapted shape, other material

and/or other joining technique.



H10 Demolition work	
	Total demolition of garage, including shallow foundation
	Location: side and rear facade Dismantling and removal of steel grilles and exterior shutters
	Location: side and rear facade Dismantling and removal of steel grilles and exterior shutters



	Location: facade Dismantle and store for reuse latticework exterior
22. Masonry	
	Location: rear facade raised extension Repair pointing glass bricks
	Location: facades general, widespread Removal of old ironwork and replacement of broken bricks, widespread Restoration category (URL 4003): 2



Location: facades general, widespread Removal of old ironwork and replacement of broken bricks, widespread Restoration category (URL 4003): 2
Location: facades general, widespread Replace weathered and failed pointing, cutting joint Restoration category (URL4006) 3a
Location: facades general, widespread Replace weathered and failed pointing, cutting joint Restoration category (URL4006) 3a




	Location: facades general Replace weathered and failed pointing, cutting joint. Replace lead Restoration category (URL4006) 3a
	Location: roof Replace weathered and fallen-out pointing chimneys, joint flat Replace lead Restoration category (URL4006) 3a
Stephen and States	Location: roof Repair cracks in chimney near left side wall Restoration category (URL4006) 2



Location: flat roof Repair affected roof beams and roof boarding Restoration category (URL 3001): 2
Location: pitched roof Repair affected parts ridge, rafters and (horizontal) roof boarding Restoration category (URL 3001): 2
Location: high roofs, general roof cantilevers with consoles, Repair affected parts: restoration category: 2. Fit missing parts: restoration category: 3a







	Location: flat roof, raised extension, rear elevation Replacing roof boarding to create a balcony
	Location: flat roof, extension, rear façade Installation of wooden cantboard
H 30 Frames, windows and doors	(Frame number: see plans in attachment)
	K01: window frame with pivot window, stone lintel Frame: restoration category: 2 Check, repair minor damage with epoxy repair. Decorative bars cast iron: Restoration category: 3a Window: restoration category: 3c Renew and make operable to open window.


















BG08 to BG12 Remove and remove lattice work. Close fastening points. Remove glazing, deepen rebate and install insulation glass. Repair hinges & locks
11 restoration category: 3c remove glazing, deepen rebate and fit monument glass. Check, repair minor damage with epoxy repair.
12 Frame/frontage restoration category: 3a Replace lower sills and bad parts Windows: restoration category: 3c Replace lower sills and bad parts Remove glazing, deepen rebate and fit monument glass. Repair and replacement of hinges and locks Repairing and replacing fall-through protection Installing draught excluder


























	Location: flat roof extension rear facade Replacing skylights (2x)
H32 Stairs and balustrades	
	Location: left side facade, 1st floor Balcony railing Top rail: entirely replaced Restoration category: 3a Bottom rail and bars: repair Restoration category: 2
	Location: front facade, 2nd floor Top rail: entirely replaced Upright handrail: entirely replaced Restoration category: 3a Bottom rail and bars: repair Restoration category: 2









	Location: high flat roof Replace zinc ridge roof, incl part of neighbouring building
	Location: balcony 2nd floor front wall Replacing zinc cladding
H34 Beglazing	
Principe detail bestaand schaal 1:5	Principle detail, installing monument glass in the existing wooden frames and windows. (existing)

















l46 Paintwork	
	Location: building general Drawing up a colour historical survey
	Location: building general Painting all wooden parts on the outer facade
<image/>	Location: building general Painting inside exterior window frames




H50 Gutters and rainwater drains	
	Location: raised extension at rear elevation. Replacing zinc guttering. Restoration category: 3a
	Location: building general Repair or replace poor sections of rainwater drains. Replace flat roof rainwater drains at rear elevation.
H 70 Electrotechnical installation	
	Installation of lightning protection system




## Frame numbering













**2e VERDIEPING** B2 - vinylzeil B1 - vinylzeil B3 - verontreiniging 25 26 27 adara Martin anna x 2.95m 24 1.00m G OTHER DE ż Ŧ Överleep 2.38m H=2.50m 23 4.95m R 21 22 .5.17m 5.92m